

Visual inspection before use

Xshielder iPhone 17 Pro Max


Before use, the following points must be checked. This ensures the device is physically intact and safe to use in potentially explosive atmospheres.

Need screws, bumpers or other spare parts? Contact us at support@xshielder.com.

NB: Never use a device that does not pass visual inspection. Defects in glass, screws, bumpers or markings can pose a risk in Ex zones.


Glass

Check that the display glass, camera glass and MagSafe glass have no cracks or breaks. If anything is shattered: do not use the device.




Bumpers (corner protection)

Make sure all four bumpers are in place and seated firmly. If one or more are missing: do not use the device.



Screws

Confirm that all visible screws are present. If one or more are missing: do not use the device.



Markings

Check that the safety markings and serial number are still visible and legible. If the markings are illegible or missing, the device must not be used until this has been rectified.

